



No. 31

2019/8/5

トイレ

床



No. 32

2019/8/5

トイレ

天井



No. 33

2019/8/5

女子更衣室

床



No. 34

2019/8/5

男子休憩室

天井

雨漏りの痕あり



No. 35

2019/8/5

男子休憩室

全体



No. 36

2019/8/5

女子休憩室

全体




No. 37

2019/8/5

女子休憩室

天井

雨漏りの痕あり



No. 38

2019/8/5

会議室

全体



No. 39

2019/8/5

会議室

天井



No. 40

2019/8/5

研修室

床



No. 41

2019/8/5

研修室

全体



No. 42

2019/8/5

研修室

天井

雨漏りの痕あり



No. 43

2019/8/5

研修室

全体



No. 44

2019/8/5

廊下

損傷あり



No. 45

2019/8/5

屋根



No. 46

2019/8/5

屋根



No. 47

2019/8/5

玄関

天井

雨漏りの痕あり



No. 48

2019/8/5

玄関

全体